PATENT Docket No.: QN1022.US

IN THE U.S. PATENT AND TRADEMARK OFFICE

First Named Inventor: Michael I. Thompson

Patent No.: 7,403,542

Issue Date: July 22, 2008

For: METHOD AND SYSTEM FOR PROCESSING NETWORK DATA

PACKETS

ATTENTION: CERTIFICATE OF CORRECTIONS BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 35 U.S.C. § 254 and 37 C.F.R. § 1.322

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attn: Certificate of Correction Branch

Dear Commissioner:

Attached hereto is a Certificate of Correction in connection with the above-identified patent. It is noted that the attached Certificate of Correction form is being filed to correct the indicated errors. The errors occurred through the fault of the US Patent and Trademark Office. Therefore, the issuance of a Certificate of Correction under 35 U.S.C. § 254 without charge to the patentee is respectfully requested.

If necessary, the Commissioner is hereby authorized in this, concurrent, and future replies, to charge payment or credit any overpayment to Deposit Account No. 11-1159 for any additional fees required.

Respectfully submitted,

KLEIN, O'NEILL & SINGH, LLP

(Customer No.: 22145)

Richa Dhindsa (Reg. No.: 65,377) 18200 Von Karman Ave., Suite 725

Irvine, CA 92612

Tel: (949) 955-1920 Fax: (949) 955-1921

Attachments: Certificate of Correction

Date: 9/9/2010

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,403,542 Page 1 of 2

DATED : July 22, 2008

INVENTOR(S) : Michael I. Thompson

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 1, line 18, delete "PACKETS". " and insert - - PACKETS", - -, therefor.

In column 4, line 44, after "includes" insert --, --.

In column 7, line 39, delete "203." and insert - - 203, - -, therefor.

In column 8, line 11, delete "201A." and insert - - 201A, - -, therefor.

In column 8, line 55, delete "PCT." and insert - - PCI. - -, therefor.

In column 25, line 19, delete "t Idle" and insert - - t idle - -, therefor.

In column 33, line 11, delete "ORDER" and insert - - Order - -, therefor.

In column 34, line 22, delete "(399A." and insert - - (399A, - -, therefor.

In column 34, line 30, delete "399G." and insert - - 399G, - -, therefor.

In column 34, line 55, delete "NCB(S)" and insert - - NCB(s) - -, therefor.

In column 35, line 66, after "equal" insert --, --.

In column 36, line 5, after "elapsed" insert - - , - - .

In column 36, line 7-8, after "ACK." delete " If the delayed ACK timer has elapsed, TTM 323 places the NCB on outbound request list to have OTP 309 send an ACK.".

In column 41, line 7, delete "_Ink" and insert - - _Ink - -, therefor.

PATENT NO. 7,403,542

No of additional copies

MAILING ADDRESS OF SENDER: KLEIN, O'NEILL & SINGH, LLP 18200 Von Karman Ave., Suite 725 Irvine, CA 92612 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Panerwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,403,542 Page 2 of 2

DATED : July 22, 2008

INVENTOR(S) : Michael I. Thompson

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 41, line 15, delete "buf cnt" and insert - - buf cnt - -, therefor.

In column 43, line 4, after "ODE" insert - - 338/OTP309/TTMI 308B.- - .

In column 55, line 21, in claim 1, delete "manner" and insert - - manager - -, therefor.

In column 55, line 33, in claim 1, delete "frames:" and insert - - frames; - -, therefor.

In column 56, line 19, in claim 5, delete "manager" and insert - - manager, - -, therefor.

In column 56, line 21, in claim 5, delete "manager" and insert - - manage - -, therefor.

MAILING ADDRESS OF SENDER: KLEIN, O'NEILL & SINGH, LLP 18200 Von Karman Ave., Suite 725 Irvine, CA 92612 PATENT NO. 7.403.542

No of additional copies

